30 Hov 68 00

25X1

112

R 300024Z NOV 68 FM NPIC WASHDC TO RUEOJFA/DIA (DIAXX-2) RUEOJFA/JCS (JRC) RUEFHQA/HQ USAF FOR AFNICAD & AFRDRP RHCOAAA/SAC (DIR) RHCOAAA/544TH ARTW OFFUTT AFB RUWMDDA/9 SRW (DCI) RUHHHQA/CINCPAC RUHHBRA/CINCPACFLT RUHHABA/CINCPACAF (DIR) RUHHRGA/CINCUSARPAC DISTRIBUTION OFFICE RUCIFGA/AERONAUTICAL SYSTEMS DIV (ASZB), WPAFB OHIO BT CABLE SEC CITE NPIC 5139 SECRET FPAB/RD REF NPIC 4579 OF 13 SEPTEMBER 1968 SHOUR. SUBJECT: EVALUATION OF GIANT SCALE MISSION QUALITY SUMMARY: THIS MISSION IS COMPARABLE TO RECENT PSG/OC RRD KEPRO 25X1 AID PAGE 2 RUEADJU 120 S E C R E T GIANT SCALE MISSIONS. CLOUDS AND HAZE OBSCURE OR DEGRADE TROD APPROXIMATELY 35 PERCENT OF THE IMAGERY. PHOTO INTERPRETATION SCIEM SUITABILITY IS CONSIDERED TO BE FAIR. EMPIRICAL GROUND RESOLUTION ESTIMATES OF THE BEST IMAGERY WEST MAST AT OPERATIONAL ALTITUDE ARE AS FOLLOWS: "25X1 Mas. A. LEFT TECHNICAL OBJECTIVE CAMERA B. RIGHT TECHNICAL OBJECTIVE CAMERA PGW LEFT OPERATIONAL OBJECTIVE CAMERA IAS RIGHT OPERATIONAL OBJECTIVE CAMERA DIA-XX4 ANALYSIS OF TECHNICAL OBJECTIVE CAMERAS COMMENTS APPLICABLE TO BOTH CAMERAS OTHER THAN THOSE MENTIONED IN REF CABLE. 25X1 THE IMAGERY DISPLAYS AN APPARENT OUT OF FOCUS (1) CONDITION AFTER EACH CAMERA OFF/ON OF AN HOUR OR LONGER. THIS CONDITION IS SIMILAR TO THAT REPORTED ON PREVIOUS MISSIONS.
B. LEFT TECHNICAL OBJECTIVE CAMERA (S/N 6403): ADVANCE CY (1) NO UNUSUAL ANOMALIES. RIGHT TECHNICAL OBJECTIVE CAMERA (S/N 6408): SANITIZED WITH TEXT (1) NO UNUSUAL ANOMALIES. ANALYSIS OF OPERATIONAL OBJECTIVE CAMERAS:

PAGE 3 RUEADJU 120 S E C R E T A. COMMENTS APPLICABLE TO BOTH CAMERAS OTHER THAN THOSE

MENTIONED IN REF CABLE:

(1) INTERMITTENT EMULSION SCRATCHES, ROUGHLY PARALLEL TO THE MAJOR AXIS, ARE PRESENT ON THE MATERIAL FROM BOTH CAMERAS. THE NUMBER AND SEVERITY OF THESE SCRATCHES IN SOME AREAS (EXAMPLE: FRAMES 701-715, LEFT OOC) CAUSED SERIOUS DEGRADATION TO THE IMAGERY.

B. LEFT OPERATIONAL OBJECTIVE CAMERA (S/N 4023): (1) EMULSION CRACKS ARE PRESENT INTERMITTENTLY BETWEEN

int com automati. downtrating an 25X1 declassification #

25X1

FRAMES 040 AND 070. FRAMES 067 AND 068 CONTAIN MINOR CREASES. A BLANK METERED AREA, 8.0 TO 18.0 INCHES IN LENGTH, OCCURS BETWEEN THE CAMERA OFF/ON FRAMES. THREE CYCLES OF THE EVENTS COUNTER OCCURRED AT THE CAMERA OFF/ON, FRAMES 2527/2528 (EVENTS COUNTER OMITTED NUMBERS 2528 AND 2529).

C. RIGHT OPERATIONAL OBJECTIVE CAMERA (S/N 4032):

(1) NO UNUSUAL ANOMALIES.

GP-1 SECRET

END OF MSG

25X1